

Beatty's Guest Ranch

View from footbridge over Miller Creek near campsites, July 8th.



Beatty's Guest Ranch

View of the same Miller Creek riparian area, July 11<sup>th</sup>, from river left.  
This material came from Marshall Canyon.



View upfan of Marshall Canyon debris fan from confluence w/Miller Creek



Photos above and below are of Miller Creek riparian area below Marshall Canyon.

New channel of Miller Creek



Beatty's Guest Ranch  
Miller Creek at the FS boundary, July 8<sup>th</sup> and 11<sup>th</sup>.



View upstream, July 8<sup>th</sup> and 11<sup>th</sup>.



View downstream, July 8<sup>th</sup> and 11<sup>th</sup>.



Beatty's Guest Ranch  
Marshall Canyon, July 8<sup>th</sup> and 11<sup>th</sup>.



View upstream of Marshall Canyon, July 8<sup>th</sup> and 11<sup>th</sup>.



View of Marshall Canyon debris fan, July 11<sup>th</sup>.


View of Marshall Canyon debris fan looking downstream at the confluence of Marshall (left arrow) and Miller Creek (right arrow), July 11<sup>th</sup>.



Looking upstream in Miller Creek, July 11<sup>th</sup>. Small debris flow snout just above confluence with Marshall Canyon.




View downstream of Beatty's Gulch, July 8th.



View downstream of Beatty's Gulch, July 11th.



View of Beatty's pond, July 8<sup>th</sup>.



View of Beatty's pond, July 11<sup>th</sup>.



View looking up Marshall Canyon, July 8<sup>th</sup>.



View looking up Marshall Canyon, July 11<sup>th</sup>. Note freshly scoured channels in upper watershed.



For more information contact:

Ann Youberg

Research Geologist

Arizona Geological Survey

416 W Congress, Suite 100

Tucson, Arizona 85719

[ann.youberg@azgs.az.gov](mailto:ann.youberg@azgs.az.gov)

520-209-4142 (direct)

520-770-3505 (fax)

